





Friendly Customer Service

If you have any difficulties after reviewing the documentation, visit our website or call 1.541.753.6645 between 9AM-5PM PT.

Visit www.OptiTrack.com for the latest software support, sample code, and product news.



V120:DUO




V120:TRIO


quick start guide

1. Install Tracking Tools Software

Download the latest software installer from the website or use software CD if included. Run the installer and follow its prompts.



2. Plug In Hardware



* Notes

- After starting Tracking Tools software, the device should be ready to track immediately.
- Licensing and calibration are automatic and built into the device.
- **Warning:** Ensure power has been disconnected from the I/O-X (breakout box) before plugging or unplugging the Camera Bar Cable. Hot-plugging this cable may damage the device.
- Windows 2000, XP, Vista and Windows 7 users must be logged in as an administrator to install the USB drivers. If you only have one user login on your computer, you probably have administrator privileges.

* Status LEDs

Left LED:

- OFF Device is OFF
- RED Device in ON
- AMBER Device is Recognized by Tracking Tools

Right LED:

- OFF Tracking/Video is NOT ENABLED
- Solid-RED Configured for External-Sync – Sync Not Detected
- Flashing-RED Configured for External-Sync – Sync Detected
- Solid-GREEN Configured for Internal-Sync – Sync Missing
- Flashing-GREEN Configured for Internal-Sync – Sync Present